100% – actual zoom indicator

F5 – zoom in – hot key for "zoom in" function
F6 – zoom out – hot key for "zoom out" function

R-Button-Point1 – mouse right button click measure position of Point 1 (first point)
L-Button-Point2 – mouse left button click measure position of Point 2 (second point)

P1x = – x coordinate of Point 1
P1y = – y coordinate of Point 1
P2x = – x coordinate of Point 2
P2y = – y coordinate of Point 2
dx = – difference between x coordinates of Point 1 and Point 2
dy = – difference between y coordinates of Point 1 and Point 2
dz = – smallest distance between Point 1 and Point 2 [mm], $dz = \sqrt{(dx^2 + dy^2)}$